

## **LUSAS 19.1 Error Fix and Modification Release Notes**

This document lists modifications, other than the New Features in 19.1, that have been made since LUSAS 19.0-3 and is correct as of 1<sup>st</sup> Feb 2022

---

### **Version 19.1-3 Built 2<sup>nd</sup> Dec 2021**

This installation is built with all revisions to r38811 plus 38926, 38834, 38851, 38862, 38864-38866, 38894-38895, 38898-38924, 38952-39034 and is referred to as r39145

### **LUSAS Modeller 19.1-3 (39058)**

#### **Errors fixed**

The following critical, major or minor issues are fixed in V19.1-3.

Vehicle Load Optimisation speed problems encountered for bridges with 4 or more spans when using a Code of Practice with a variable intensity lane load (CS 454 ALL Model 2, BD21/01, BD34/90, BD37/01) (CR29439)
Vehicle Load Optimiser loads only one carriageway instead of both carriageways when using CS458 (29416)
When using the legacy "average just what's visible" option together with transformations, results from elements in the same feature are averaged regardless of visibility (29407)
Results not shown for inspection locations when the extent is not 'full model' (29389)
Inspection location results not shown in some beams with rigid zones (29369)
Surface cannot be swept with a rotation to create a volume when formed from a combined line lying on the axis of rotation (29306)
Combined lines forming part of a volume definition may be lost during merge after copy with mirror transformation (29305)
Graphing a slideline component in the absence of any Slideline groups leads to an error (29287)
Zero spring stiffness incorrectly tabulated when support with stiffness per unit length is assigned to line (29280)
Graph through 2D giving fails to display results for certain cases (29277)
RC frame design offers unaveraged nodal contours, but draws nothing (29271)
LPI command attr.getMeshDivisions does not work in VBS - Cannot get mesh divisions (29267)
Modeller crashes when Graph properties are repeatedly edited (29260)
Suppressing messages by way of LPI command fails to suppress messages from Beam/Shell slice resultant tool (29239)
Tools > Mesh > Distance between nodes reports the undeformed distance between nodes when the deformed distance was expected (29238)
Visual Fortran run-time error when contour or values results are viewed in a model with mixed resultant beams and cross-section beams (29215)
Modeller crashes while attempting to display results from a model with mixed resultant beam and cross-section beam elements in use (29214)
Stress at inspection location is not shown for solid elements (29195)

RLO should be able to provide vertical loading patterns for deck models which are not horizontal (29175)
Cannot assign geometric or material attributes to mesh only model (29098)
When loading a pre-V19 file, solution options that were specified "per analysis" are discarded and must be entered again (29083)
Cannot use orthotropic material with 2D Axisymmetric Thick Shells, although it is valid (29021)
When two primary components are selected in the print result wizard, the results in the summary tab differs from the main results table (29015)
Temperature dependent properties cannot be set in a hygro-thermal material (29003)
Load curve analysis not marked for solving after load assignments changed (28980)
LPI command to get 'Reaction' results from a point (rather than a node) is needed (28937)
Window summary shows incorrect min/max when display precision is turned all the way down to zero decimal places (28902)
Cannot delete a custom VLO Vehicle from the Utilities tree (28893)
Setting a particular beam fibre (e.g. CHS) active can erroneously show beam stresses on other section types (e.g. RHS), if that other section type is assigned in another analysis (28890)
'Prescribed displacement' and 'prescribed tempertaure' loading set to 'Free' does not overwrite a prior use of 'Prescribed displacement' and 'prescribed tempertaure' loading as expected (28877)
Modeller crashes when editing quadrilateral cross-section vertices in a Bridge Deck (Grillage) section from the Girder tab > Section Details > Cross Section page (28754)
RC Frame Design gives error message 'Reinforcement material selected in the RC Material Attribute is incorrect...' if the attribute has been defined from the LPI, or defined by copying and pasting the entire grid contents (28732)
User defined composite section with beam and slab - contour fibre stresses plot for 'set name active' but not 'set fibre active' (28666)
When using cross-section beams, the Section Details > Cross section tab has misleading labels (28375)
Steel composite bridge deck design to AASHTO 8th - 2nd order Amplification Factor applied even if GNL is on (27915)

A number of fixes for cosmetic issues, documentation issues, installation issues, and development requests are also provided in V19.1-3. Users with a reference number provided by LUSAS Customer Support may identify these from the following list:

29481, 29469, 29408, 29362, 29288, 29284, 29272, 29234, 29216, 29159, 29140, 29099, 29075, 29058, 29056, 29042, 29007, 28993, 28990, 28972, 28964, 28930, 28926, 28919, 28917, 28896, 28871, 28858, 28855, 28800, 28633, 28190

## LUSAS Solver 19.1-3 (7303)

### Errors fixed

The following critical, major or minor issues are fixed in V19.1-3.

Eigenvalue buckling analysis branched from nonlinear analysis fails unless GNL options switched on (29448)
Piecewise linear elastic joint material does not work when connected to Quadratic shells (QTS8) (29302)
Thick cross section beam analysis fails with system error (29105)

Lead Rubber Bearing (LRB) joint material - fails convergence due to "incremental energy is negative" (29081)
Applied load is unexpectedly applied in local (rather than global) axes for a joint element with non-zero length (28958)
Solver fails with no error message under certain specific circumstances (28940)
Time taken to write element records to MYS file is significantly slower than in v18.1 (28868)
Lead Rubber bearing joint material response to unloading is inaccurate, requiring automatic decrementation to take smaller steps (28865)

---

## Version 19.1-2 Built 22<sup>nd</sup> June 2021

This installation is built with all revisions to r37863 plus 37870, 37873, 37933, 37934, 37976, 37999, 38107 and is referred to as r38108

### LUSAS Modeller 19.1-2 (37990)

#### Errors fixed

The following critical, major or minor issues are fixed in V19.1-2.

Results loaded under the wrong analysis when loading model or using "open available results" (28884)
Slice resultants contours not displayed when part of the model is invisible (28873)
Model Merge does not obey merge loadcases when results are loaded for the currently open model despite the loadcase names matching (28854)
Cannot mesh with a mix of 3- and 4-node space membrane elements (28840)
RC Frame Design loadset errors loading data (28839)
Discrete Load Assignment dialog should allow Compound Rotation-only transformations as Load Transformations (28828)
Deleting Compound loads as part of running a second VLO run crashes modeller (28827)
Load assignments not updated when transformation is edited (28824)
Tendon profile definition in 2D planes do not handle changes within X coordinates (tendon cannot pass the same X twice) (28802)
Steel composite bridge wizard - error generating bridge - unable to generate design member attributes (28786)
Grillage wizard does not work if Grillage startup template is chosen in new model (28507)
No model results available for contours / diagrams, after viewing beam shell slice results (28455)

A number of fixes for cosmetic issues, documentation issues, installation issues, and development requests are also provided in V19.1-2. Users with a reference number provided by LUSAS Customer Support may identify these from the following list:

28949, 28864, 28863, 28862, 28861, 28857, 28856, 28843, 28841, 28837, 28833, 28829, 28821, 28807, 28686, 28344

#### No changes to Solver (7205)



---

## Version 19.1-1 Built 14<sup>th</sup> May 2021

### LUSAS Modeller 19.1-1 (37707)

#### Errors fixed

The following critical, major or minor issues are fixed in V19.1-1.

When initial deformations are in use, data tip and labelled nodal positions will include those values incorrectly multiplied by the chosen scale factor (28804)
A model file that contains a compound load that contains a compound discrete load can be saved, but cannot be opened in V19.0 (28791)
"Cannot assign all the load from patch load to the search area" warning message shown erroneously (28789)
Analysis that was solved is marked as 'unsolved' in the 'Solve now' window (28758)
A valid face load assignment leads to an error at tabulation due to the presence of a combined line (28715)
IMDPlus analysis fails when the model name contains spaces or other punctuation characters (28694)
Selecting nodes with the values, geometry and mesh drawing layers visible can cause Modeller to close unexpectedly in certain models (28687)
When assigning an irregular mesh to a surface, the 'background grid' option is greyed out when it should be available (28668)
Deleting background grids can cause Modeller to crash (28667)
AASHTO creep and shrinkage material - incorrect value of hr (V/S ratio) in tabulation (28646)
Branched analysis - changing the loadcase order incorrectly changes the loadcase that is subsequently used as the base for branches, initial deformations, and restarts (28638)
Cannot define orthotropic elastic component using variations (28622)
Graph wizard, modal expansion loading option does not allow results from linear analyses to be selected (28596)
Mohr-Coulomb friction Interface cohesion curve data not stored on OK (28594)
Thermal analysis tabulation fails in a coupled analysis when profile set variations are used within the structural material definition (28588)
Target stress/strain loading intermittently fails to tabulate (28582)
Deleting an analysis in a specific model leads to a crash (28580)
After deleting a load case that is included within a range, loads are shown as assigned but are not tabulated (28568)
Composite deck design fatigue checks carried out at incorrect flange (28557)
RC Slab designer with Clark-Neilsen: Australian standard capacity reduction factor for tension is incorrectly used for cases with bending and axial compression (28545)
Modeller won't load results unless spaces in the filename are replaced with underscores (28543)
BS5400-3 Steel Designer: results not displayed for certain locations because the plastic neutral axis is incorrectly reported as outside the web (28538)
Envelopes and combinations do not give results when elements are deactivated in a deconstruction sequence (28528)
CSA-S6-14 steel design gives incorrect and unconservative results for cantilever members (28501)

Error writing support attributes when lift off supports in two different directions are assigned to two connected surfaces (28476)
Eigen buckling analysis branch will not run because no load is tabulated (28469)
RC frame design member report not displayed, with error 'populateSectionsList: Object reference not set to an instance of an object' (28459)
Flexural-torsional buckling checks not included for channel sections for CSA-S6-14 steel design (28376)
Solve now (multiple analyses) does not work for models containing the old (V14.1) manual influence (28337)
Meshing fails after assigning joints in a model half a million units for the origin (28322)
Modeller tabulates a profile variation as a profile variation for some elements where solver does not support profile variations (instead, Modeller should evaluate the variation, and tabulate numbers) (28321)
2D reciprocal influence analysis will not run, giving the message 'Non structural node - variable 1 has been defined as a spring support' (28319)
Linear with creep/shrinkage model 86: Cement type is not stored (28318)
Cannot access RC frame design after updating from v19.0-2 (28307)
Cross section beam plastic strains are incorrect and should not be available (28299)
A warning is needed when viewing stresses on beams with nonlinear materials (28284)
Temperature profile to EN1991-5 Approach 2 Type 2 Deck - error in cooling curve value dt2 (28262)
Mismatch of bridge longitudinal axis imported from LUSAS to steel/composite deck designer (28254)
Cannot use graph wizard for load cases inside a branch (28243)
Slicing for a basic combination fails in some models where design facilities are in use (28240)
Can't use steel composite bridge wizard without composite deck design licence in place (28215)
Modeller can fail to tabulate COUPLE commands in a hygro-thermal-structural analysis inherited from v18.0 (28174)
Vehicle Load Optimiser: launching the CS454 model 2 optional code settings dialog gives spurious error message (28122)
Modeller fails to launch after a Windows 10 Enterprise update (28107)
AASHTO tendon loss - shrinkage using commentary - V/S ratio should be capped at 6" (28084)
When the PRW extent is set to "group", the "total contributions" and "examine contributions" dialogs averaging calculation can include elements outside of that scope, leading to apparently erroneous values. (28027)
Loadcase created from a smart combination sometimes does not include gravity (28013)
InstallLicense.exe LUSAS network license Installer fails to run (27989)
Lift off spring supports fail at tabulation due to conflicting assignments on surfaces which share a line (27971)
Supports in a branched analysis not shown correctly (27902)
Saved view in report writer: Window summary can be incorrect (27888)
The graph through 2D facility generates multiple curves. For axisymmetric elements, some of those curves are not relevant and should be removed (27820)
Using DMI in conjunction with beam shell slicing can cause a crash (27789)
Design combinations for Can/CSA-S6-06 creates an SLS combination when an FLS combination was requested (27773)

Temperature profile loading to AS5100, invalid cooling profile for ballast $\geq 300\text{mm}$ (27751)
Graph through 2D - slice resultant for axisymmetric solid uses same approach as plane strain, which can lead to incorrect answers (27644)
Composite deck design to AASHTO should consider axial forces (27530)
Composite deck design to AASHTO should determine if the slab is cracked from the total loads rather than phase by phase (27529)
Crash creating / opening any model in 64bit Modeller on PCs where shaders are not available (27424)
A change in supports, from one loadcase to the next, can be overlooked when prescribed displacements are in use (27338)
Supports can sometimes be wrongly tabulated in models where the support is reassigned in a different analysis (26831)
Can't find library sections due to registry settings for decryption (26266)
Chinese characters incorrectly interpreted from VBScript files (23014)

A number of fixes for cosmetic issues, documentation issues, installation issues, and development requests are also provided in V19.1-1. Users with a reference number provided by LUSAS Customer Support may identify these from the following list:

28799, 28776, 28757, 28728, 28669, 28665, 28664, 28634, 28629, 28620, 28618, 28616, 28587, 28575, 28564, 28551, 28511, 28500, 28498, 28486, 28480, 28477, 28462, 28440, 28435, 28378, 28360, 28340, 28336, 28335, 28332, 28331, 28326, 28311, 28308, 28273, 28241, 28226, 28222, 28176, 28162, 28160, 28147, 28129, 28124, 28065, 28049, 28025, 28009, 28001, 27981, 27969, 27960, 27959, 27955, 27942, 27938, 27899, 27895, 27875, 27871, 27869, 27852, 27848, 27845, 27838, 27788, 27726, 27716, 27715, 27685, 27673, 27668, 27655, 27640, 27634, 27622, 27621, 27613, 27595, 27580, 27577, 27539, 27534, 27517, 27485, 27464, 27443, 27429, 27349, 27262, 26894, 26687, 26686, 26685, 26475, 26342, 26309, 25882, 25460, 23738, 23278, 21273, 20906, 20364, 20363, 19844, 19659, 19636, 19479, 17341, 16554, 16292, 16183, 12114

## LUSAS Solver 19.1-1 (7205)

### Errors fixed

The following critical, major or minor issues are fixed in V19.1-1.

Eigenvalue buckling analysis using '1-1/buckling load' shows wrong load factor in treeview (28312)
Thick cross section beam analysis fails with user section (28293)
System parameters are overwritten if more than one sequential restart analysis is performed (28258)
AASHTO creep and shrinkage material using commentary V/S ratio should be capped at 6" (28155)
Frictional joints in a thermal analysis fail with database errors (28150)
Frontal Solver fails with system errors in a linear analysis if it is not possible to solve all loadcases at the same time. (28040)
Linear thick beam elements (BMI21) require many divisions for displacement convergence with non-symmetric sections (28026)
Lift off supports with Frontal Solver fails with system error (27991)
Force interpolation is inaccurate in BMI31 elements compared to BMI21 (27854)
Activation and deactivation solution does not allow for step reduction unless automatic incrementation is in use (27483)